



Florida Department of Environmental Protection  
Twin Towers Office Bldg. 2600 Blair Stone Road, Tallahassee, Florida, 32399-2400  
Division of Waste Management  
Petroleum Storage Systems  
Storage Tank Facility Compliance Assistance Site Inspection Report

### Facility Information:

Facility ID: 8517300 County: VOLUSIA Inspection Date: 03/01/2024  
Facility Type: A - Retail Station  
Facility Name: CHEVRON-TROPICAL # of inspected ASTs: 0  
2995 HWY 44 & I-95 USTs: 2  
NEW SMYRNA BEACH, FL 32168 Mineral Acid Tanks: 0  
Latitude: 29° 0' 47.81"  
Longitude: 80° 59' 30.31"  
LL Method: DPHO

### Inspection Result:

Result: In Compliance

### Signatures:

TKOREP - ORANGE CNTY ENVIRONMENTAL PROTECTION DIVISION (407) 836-1499

### Storage Tank Program Office and Phone Number

Matthew S Kidder

Leo

Inspector Name

Representative Name

Inspector Signature

Representative Signature

Principal Inspector

ORANGE CNTY ENVIRONMENTAL PROTECTION  
DIVISION

Owners of UST facilities are reminded that the Federal Energy Policy Act of 2005 and 40 CFR 280 Subpart J requires Operator Training at all facilities by October 13, 2018. For further information please visit:  
<https://floridadep.gov/waste/permitting-compliance-assistance/content/underground-storage-tank-operator-training>

### Financial Responsibility:

Financial Responsibility: INSURANCE

Insurance Carrier: COMMERCE AND INDUSTRY INSURANCE COMPANY

Effective Date: 08/20/2023

Expiration Date: 08/20/2024

## Completed System Tests

Type	Date Completed	Results	Reviewed	Next Due Date	Comment
Annual Operability - Line Leak Detector	12/07/2023	Passed	03/15/2024	12/07/2024	3 MLLDs
Annual Operability - Overfill Protection	12/07/2023	Passed	03/15/2024	12/07/2024	3 Flapper Valves
Annual Operability - Release Detection	12/07/2023	Passed	03/15/2024	12/07/2024	Veeder Root Cert/Sensors
Integrity Test - Dispenser Sump	10/19/2022	Passed	05/04/2023	10/19/2025	testing by Petroleum Technicians
Integrity Test - Double-walled Spill Bucket	03/01/2024	Passed	03/13/2024	03/01/2027	DSL Spill Bucket Integrity Tested Post Repairs
Integrity Test - Double-walled Spill Bucket	12/07/2023	Passed	03/15/2024	12/07/2026	3 DW Spill Buckets
Integrity Test - STP Sump	10/19/2022	Passed	05/04/2023	10/19/2025	testing by Petroleum Technicians

## Reviewed Records

Record Category	Record type	From Date	To Date	Reviewed Record Comment
Three Years	Monthly Maint. Visual Examinations and Results	01/05/2023	03/04/2024	MVIs

## Site Visit Comments

03/01/2024

Report will be emailed to: khaledkoleilat@bellsouth.net, lauren@daytonafamilylaw.com, jim@petroleumtechnicians.com, and bill@goodenviro.com.

On site for a compliance assistance inspection.

Petroleum Technicians Inc (PCC#056694) is re-threading the diesel spill bucket riser.

Concrete around the diesel fill port will be exposed during the process.

The spill bucket will need to be removed in order to re-thread the riser.

The existing double walled spill bucket will be re installed, and integrity tested once the repairs are made.

G&S Environmental Services Inc is performing soil assessment during the repairs.

OVA's were collected at 1 foot and two foot intervals to the top of tank.

OVA's reading were under 10 PPM.

## Inspection Comments

03/01/2024

Integrity testing for the double walled spill bucket post riser repairs has been provided.

A Certified Contractor's Form shall be provided for the work that has been completed.

## Inspection Photos

Added Date 03/01/2024

Site Photo



Added Date 03/01/2024

Diesel Spill Bucket Excavation



Added Date 03/01/2024

Soil Boring Location



Added Date 03/01/2024

Diesel Spill Bucket Removed For Riser Repair

