

Address	Bldg #	Unit #	Bed	Bath	Range	Fridge	Furnace		Water Heater		Flooring	Walls	Windows	Bathroom	Notes
							Condition	Date	Condition	Date					
1801 10th	Building 1	Unit 1	2	1	Average	Average	Good	2010	Good		Good	Very Good	Average	Good	
1801 10th	Building 1	Unit 2	2	1	Average	Average	Poor		Good		Average	Very Good	Average	Average	
1801 10th	Building 1	Unit 3	2	1	Average	Average	Average		Good		Average	Average	Average	Good	
1801 10th	Building 1	Unit 4	2	1	Average	Average	Poor		Very Good	2014	Good	Good	Average	Average	
1801 10th	Building 2	Unit 10	2	1	Average	Average	Good			2004	Poor	Good	Poor	Good	
1801 10th	Building 2	Unit 5	2	1	Average	Average	Average		Very Good	2015	Good	Very Good	Average	Very Good	
1801 10th	Building 2	Unit 6	2	1	Average	Average	Poor		Good		Good	Very Good	Average	Good	
1801 10th	Building 2	Unit 7	2	1	Average	Good	Good		Very Good	2015	Very Good	Very Good	Average	Very Good	
1801 10th	Building 2	Unit 8	2	1	Good	Very Good	Good			1999	Very Good	Good	Average	Very Good	
1801 10th	Building 2	Unit 9	2	1	Poor	Average	Good			1991	Good	Very Good	Average	Good	
1801 10th	Building 3	Unit 11	2	1	Average	Average	Good		Good		Average	Good	Average	Good	
1801 10th	Building 3	Unit 12	2	1	Good	Good	Good			1996	Poor	Average	Average	Good	Plus mini fridge
1801 10th	Building 3	Unit 13	2	1	Average	Average	Poor		Good		Good	Very Good	Average	Average	
1801 10th	Building 3	Unit 14	2	1	Good	Good	Average	1997		2010	Average	Very Good	Average	Good	
1801 10th	Building 3	Unit 15	2	1	Average	Average	Good		Good		Good	Very Good	Average	Average	
1801 10th	Building 3	Unit 16	2	1	Average	Average	Poor		Good		Good	Good	Average	Good	
1801 10th	Building 4	Unit 17	2	1	Good	Good		1997		1997	Average	Good	Average	Good	
1801 10th	Building 4	Unit 18	2	1	Good	Good	Average			1997	Average	Very Good	Average	Good	
1801 10th	Building 4	Unit 19	2	1	Good	Good	Good		Good		Very Good	Very Good	Average	Good	
1801 10th	Building 4	Unit 20	2	1	Average	Average	Very Good		Average		Good	Good	Average	Good	
1801 10th	Building 4	Unit 21	2	1	Good	Good	Very Good	2009	Very Good		Good	Very Good	Average	Good	
1801 10th	Building 4	Unit 22	2	1	Good	Average	Good			1997	Good	Very Good	Average	Average	
1801 10th	Building 5	Unit 23	2	1	Good	Good		1997		1997	Good	Very Good	Average	Good	
1801 10th	Building 5	Unit 24	2	1	Average	Average	Average		Good		Average	Very Good	Average	Good	
1801 10th	Building 5	Unit 25	2	1	Good	Average		1997		1996	Very Good	Very Good	Average	Good	
1801 10th	Building 5	Unit 26	2	1	Average	Average	Average		Good		Average	Good	Average	Very Good	
1801 10th	Building 5	Unit 27	2	1	Average	Average	Average		Average		Average	Very Good	Average	Good	
1801 10th	Building 5	Unit 28	2	1	Good	Good	Average			1997	Average	Very Good	Average	Good	
1800 9th	Building 6	Unit 1	2	1	Good	Average		1996		2011	Very Good	Good	Average	Good	
1800 9th	Building 6	Unit 2	2	1	Average	Very Good	Poor			1999	Very Good	Good	Average	Good	
1800 9th	Building 6	Unit 3	2	1	Average	Very Good	Poor			1999	Good	Very Good	Average	Good	
1800 9th	Building 6	Unit 4	2	1	Good	Very Good	Poor			1996	Average	Good	Average	Good	
1800 9th	Building 6	Unit 5	2	1	Average	Very Good	Good			2003	Very Good	Very Good	Average	Good	
1800 9th	Building 6	Unit 6	2	1	Very Good	Very Good	Poor			2009	Very Good	Very Good	Average	Good	
1800 9th	Building 7	Unit 10	2	1	Average	Average	Good			1997	Good	Good	Average	Average	Window AC unit
1800 9th	Building 7	Unit 7	2	1	Average	Good	Poor			2004	Good	Very Good	Average	Good	
1800 9th	Building 7	Unit 8	2	1	Average	Average	Poor		Average		Good	Very Good	Average	Good	
1800 9th	Building 7	Unit 9	2	1	Average	Average	Average		Good		Average	Very Good	Average	Good	
1800 9th	Building 8	Unit 11	2	1	Average	Average	Average			1996	Good	Very Good	Average	Average	
1800 9th	Building 8	Unit 12	2	1	Average	Average	Poor	1996		2011	Average	Good	Average	Good	
1800 9th	Building 8	Unit 13	2	1	Average	Average	Average			1997	Average	Very Good	Average	Average	
1800 9th	Building 8	Unit 14	2	1	Average	Average	Very Good			1996	Very Good	Very Good	Average	Average	
1800 9th	Building 8	Unit 15	2	1	Average	Average	Very Good			1996	Average	Very Good	Average	Average	
1800 9th	Building 8	Unit 16	2	1	Average	Average	Poor			2002	Good	Good	Average	Good	
1800 9th	Building 9	Unit 17A	0	1			Poor			2002	Poor	Average	Average	Good	Office space, small office, 1/2 bath
1800 9th	Building 9	Unit 17B	3	2	Poor	Poor	Poor			1996	Average	Average	Average	Average	2 small bedrooms, one very large
1800 9th	Building 9	Unit 18	2	1	Average	Average	Poor			2007	Good	Very Good	Average	Average	
1800 9th	Building 9	Unit 19	2	1	Poor	Poor	Average	2002		2006	Good	Very Good	Very Good	Poor	19-20 are connected on the main floor
1800 9th	Building 9	Unit 20	2	1			Very Good		Poor		Good	Good	Very Good	Average	AC, connected with 20-21 up and down
1800 9th	Building 9	Unit 21	2	1	Very Good	Very Good	Very Good	2010	Poor		Very Good	Very Good	Very Good	Average	
1800 9th	Building 10	Unit 22	2	1	Average	Average	Poor			1996	Average	Very Good	Average	Average	
1800 9th	Building 10	Unit 23	2	1	Average	Average	Poor			1997	Average	Very Good	Average	Average	
1800 9th	Building 10	Unit 24	2	1	Average		Poor			2009	Good	Good	Average	Average	No fridge
1800 9th	Building 10	Unit 25	2	1	Very Good	Very Good	Good			2004	Very Good	Very Good	Average	Good	
1800 9th	Building 11	Unit 26	2	1	Average	Average	Poor			2004	Average	Poor	Poor	Average	
1800 9th	Building 11	Unit 27	2	1	Average	Average	Poor			1997	Average	Poor	Average	Average	
1800 9th	Building 11	Unit 28	2	1	Average	Average	Poor			2003	Poor	Poor	Poor	Average	
1800 9th	Building 11	Unit 29	2	1	Average	Average	Poor			2005	Average	Very Good	Poor	Average	
1800 9th	Building 11	Unit 30	2	1	Average	Average	Poor			2006	Average	Very Good	Average	Average	
1800 9th	Building 11	Unit 31	2	1	Average	Average	Poor			2010	Good	Very Good	Average	Average	